Friday, 2/17/2006 8:07:45 AM

Linda Lacelle User:

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 25877

Estimate Number

: 10804

P.O. Number

This Issue

Prsht Rev.

First Issue

: 2/17/2006

: NC

: //

: 00015

Previous Run

Written By

Comment

Checked & Approved By

SER PROJE DATE & USE.

Type

S.O. No. :

Drawing Name

: K10008/K10006

Part Number

: Z CUSTOM

Drawing Number

: UPDATE PAPERWORK

Project Number

Drawing Revision Material

: NA : NIA : NIA

Due Date

: 2/24/2006

Qty:

1 Um:

Each

Additional Product

Job Number:



Seq. #:

1.0

Machine Or Operation:

Description:

PACKAGING RESOURCE #1

PACKAGING 1

Comment: PACKAGING RESOURCE #1

REMOVE FROM STOCK: K10006

BUS 271 /0 X B21/82 2X

B23603 2x

K10008 B25584 8 X

PACKAGING RESOURCE #1

CX06102120

2.0

Comment: PACKAGING RESOURCE #1

ADD NEW PAPERWORK TO KITS

DSI9320 REV.A

ENSURE BATCH NUMBERS MATCH WITH BOXES

INSPECT

C 206102120

3.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Sur oblozlez **INSPECT LEVEL 21**



Job Completion



Page 1

ENGINEERING CHANGE NOTICE

				1
	ļ	<u> </u>		ECN#: 776
				1.0
Project No: カ3ラローラネタ				
Project Name: BEALPAW [WSTALLATIA]				
	<u> </u>	(Proj. Manager))	
₹V.A	٦	o Allow Cent	TEL CLAMD HOLES .	Oguoh 3d GT
Yes	Nρ	Responsible	To happen by:	Complete
٠.	17			
17.		K7	06.07.20	
1				
,	7	113	06.02.20	
1				
1		87	Ob 02,20	
T .	1			
1./		K)	\$6.07.20	00:02.16
1 -	./	, -		()
J		K)	06-07 70	06.02, 16 98
<u> </u>	7	<u> -</u>		0
	7			
	1			<u> </u>
	7			
	丁			
	7			
	7			
 	7			
	1			
	Ť,			
	J.			
	/			
1	<u> </u>	V\ /i /	06 02 20	
7		W///		
-	7	YS/LL	00.02.20	
	7			
	Y /		<u> </u>	
/	V	8"	46.62 201 1	06.02.16
	—	<u> </u>	00.07.70	06.02.16 13
	-/			
	-/-			
	-	<u> </u>		
	7		_	
	"	·	 	
i	7			
. ILC 106) 1-	าร์	In STOCK SI		9320 RBV A.
	Yes J J J J J Li Oob)	Yes No	Yes No Responsible Yes No	Approved By: (Proj. Management if reqd) EV.A TO ALLOW CENTEL CLAMP HOLES Yes Np Responsible To happen by: YES Np Responsible To happen by: YES Np Responsible To happen by: YES Ob. 02.20 YES OB. 0

ECN Complete:	Date:
LON Compicio.	Date

DART AEROSPACE LTD	Work Order:	
Description: Custom W/O to update paperwork	Part Number:	K10006
ECN 749		K10008
Dwg: N/A		
Ref: N/A		Page 1 of 1

Step	Location	Procedure	Ву	Date
1	DC -	Issue Traveler	+	05.10.24
2	ST	Remove from finished inventory Qty Part Number Description K look		
3	PK	Add new Argentina STC CTS-0508.13 (A) to Kits in stock. Do not remove older paperwork.	9	05/12/01
4	PK	Ensure paperwork and P/N's match with boxes.	/_	25/12/63
5	QC5	Inspect work to Step 4	CL	5/12101
6	ST	Return to finished inventory	1	05/12/01
7	AC	Cost / part:	L	/
8	DC	Close W/O Inspect Level 21		05/12/02
	(Note:	Attach a copy of Custom W/O to each of the W/O's listed in Step 2	above)	

Rev	Date	Change	Revised By	Approved
Α	05.11.24	New Issue	KJ	